# Cell5050 – Solder Connections

Please solder the cables on the red marked points.
On the blue side there is „-" On the grey side „+"

Be careful when soldering and don't use too much
pressure, otherwise you can break the cell easily.