

QUALITEK®

Lead Free Tip Tinner

DESCRIPTION

Tip Tinner is a mixture of solder powder and thermally stable, oxide-reducing compounds. Tip Tinner provides better cleaning and re-tinning of highly oxidized soldering iron tips than wet sponge or rosin-cored wire.

APPLICATION METHODS

While maintaining soldering iron at operating temperature, roll or wipe soldering iron tip over the surface of Tip Tinner for a short time. Prolonged contact may create excessive fumes. Under normal usage, the fumes are very minimal and usually stop within seconds after soldering iron is withdrawn from the Tip Tinner. The residue remaining after heating is minimal and non-corrosive. It can be readily removed by wiping with a wet sponge.

PACKAGING & AVAILABILITY

Tip Tinner is available in various lead-free alloys: SnAgCu, SnAg, SnBi, SnCu. Tip Tinner is packed in 1 ounce cans.

STORAGE & DISPOSAL

Tip Tinner should be store in a cool, dry place. Dispose of in accordance with local regulations.

SHELF LIFE

Indefinite

Qualitek ® is a trademark of Qualitek International, Inc.

TEL: (630) 628-8083 FAX: (630) 628-6543 E-MAIL: solder@qualitek.com HOME PAGE:http://www.qualitek.com HEADQUARTERS: 315 Fairbank St., Addison, IL 60101 U.S.A. WORLDWIDE BRANCHES: UNITED KINGDOM – CHINA – PHILIPPINES – SINGAPORE



AN ISO 9001:2008 CERTIFIED COMPANY

This data is based on information that the manufacturer believed to be reliable and offered in good faith. Qualitek International, Inc. makes no warranties expressed or implied as to its accuracy and assumes no responsibilities and liabilities arising out of its use by others as conditions and methods of use of the products is beyond the control of Qualitek International, Inc. The user must determine the suitability of the product before using it on a commercial basis. The warranties extend only to the conformity of the product to the physical descriptions. In no event will Qualitek International, Inc. be responsible for special, incidental and consequential damages whether the claim is in contract, negligence or otherwise.

Rev: 052511-lftiptinner Consult MSDS for health and safety information