

KH 20 **- Passiv Safety Rest for FE-Irons**

BestellNr.:0051502099



Safety Rest for FE 50, FE 50M, FE 75 and FE 80

The Weller Zero-Smog Systems put an end to air pollution caused by soldering, adhesives and laser work. In all of these applications fumes or fine particles are released into the work place atmosphere which are hazardous to staff exposed to them. The Weller Zero-Smog Systems' combination of pumps, electronic controls and filters removes this hazard.

Top Attributes

- Safety Rest for FE 50, FE 50M, FE 75 and FE 80

Technical Data

Target application	Electronic
On/off indicator	No
Build in Light	No

Packaging information

Shelf pack size (Units per shelf pack)	Single
Set	No